




# Webster County

Webster Springs Elementary School





Webster Springs ES Aerial



Below: Ponding water causes leaks, which lead to interior damage.

Above & Below: Significant ponding on portions of the roof lead to widespread leaks.



Left: If water penetrations in roof are not repaired in a timely manner, damage to walls and floors can occur.

